

- 1. The accommodation ladder at starboard is shown, and is symmetrical with the accommodation ladder at port.
- is symmetrical with the accommodation ladder at port.
 2. Accommodation ladder is 55° maximum to horizontal, in this scope, all revolving parts should work flexibly.
 3. Axis of axle, axle of revolving platform and axle of ladder turnover appliance should be in alignment.
 4. All steel parts to be galvanized.
 5. 2 sets per ship (half symmetry), this material list record one shipboard quantity.

NOTE: Drawing for illustration purposes. See chart below for details of parts.

		^{hitect} 3.K	Inspector J.B			JLPSHUNG 1959	
	LU 8400		- FIXEI	DAR	C		
NO.	PART		MARK		QTY.		MATERIAL
1	Upper Platform				1		Steel
2	Davit for ACC. Ladder			1			Unit
3	Close Bracket				3		Unit
4	Winch				1		Unit
5	Side Roller			1		Unit	
6	ACC. Ladder		1			Unit	
7	Fender wood		1			Unit	
8	Hoisting Ladde	1			Unit		
9	Post		1			Steel	
10	Support				3		Unit